WHEP SUMMARY (City Project 03-5602)

Name	WHEP #	City ID #	Vegetation Score															Invertebrate Score														Comments
			2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015		2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	
Morraine Way Pond	EP-1	16-31-A	P - M	P														M-P	M													Fairly dry and difficult to monitor
Birch Island Lake	EP-2	04-13-B	M															E														Wrong location, were to monitor a wetland adjacent to the lake (EP-6)
Duck Pond West	EP-3	05-33-A	M	M														M	M													
Dell Road Pond	EP-4	18-44-A	M	M	P													E	M	E												City reference wetland
Nesbitt Park Pond	EP-5	24-22-A			P	P+														M	M											
Birch Island Pond	EP-6	04-14-B		M	M-P														P	P												Fairly dry and difficult to monitor
Duck Pond South	EP-7	08-12-A			M	M	M													M	E	E										Research site for Univ. of Wisconsin for deformed frogs
Water Plant Mitigation Site	EP-8	5-23-E				M	M-P	M													M	M-P	E									Constructed in 2003 as a wetland mitigation bank site.
West Round Lake Pond	EP-9	08-23-A				M	M	M-M						M	M						P	P	M-E						P	M		Received barley straw in 2006 and 2007 for algae treatment - excavated in winter 2009/2010
Highview Pond	EP-10	30-23-A					P+							M								E							E			Wrong location, were to go to Settlers West Pond A (EP-12)
Glenshire Mitigation Site	EP-11	09-12-A						P	M							M							M	M							P	Wetland expanded in 2003 for use as a wetland mitigation bank site
Settlers West Pond A	EP-12	30-23-C						M	M														M	P								Expanded in 2006 for mitigation within Settlers West Development
Wooddale Church	EP-13	01-33-A							M-P															E-E								Stormwater ponding area
Anderson Lakes West	EP-14	13-32-A							M					M	M									M					E	M		To be excavated and cleaned out for the Anderson Lakes project - use for baseline.
Hidden Ponds Park North	EP-15	07-23-A								M	M														P	M						
Hidden Ponds Park South	EP-16	07-24-F								M	M														M	M						
Round Lake Park Southwest	EP-17	08-32-A								M				M	P										P				P	M		Stormwater wetland - excavated winter 2009 for additional treatment capacity
Westgate Conservation Area	EP-18	09-33-B								M-M	M														E-M	M						Wetland mitigation site
ADC Wetland Mitigation Site 1	EP-19	15-31-C									M															M						Wetland mitigation site
Round Lake Park Northeast	EP-20	08-13-A										M	M														M-E	M				
Round Lake Park East	EP-21	08-42-C										M	P														M	M				
ADC Wetland Mitigation Site 2	EP-22	15-13-E										M	M		E												M	M		M		
Braxton Lane Pond	EP-23	20-24-A										M	E														M	P				Permission to enter from Torkelson property
Round Lake Park Northwest	EP-24	08-23-A											M			P												P			P	
Staring Lake Pond	EP-25	22-13-B												M		M													P		P	Pre-monitor in 2012 prior to starting CWF Grant project with addition of an Iron Enhanced Sand Filtration Bench in Fall 2013
Rice Marsh Lake Park West	EP-26	18-41-A													E	M														M	E	
Purgatory Creek Park Pond	EP-27	15-14-B													P	M														E	P	
Purgatory Creek Park Pond West	EP-28	15-13-G																														

P = Poor

M = Moderate

E - Excellent